

Maryland Historical Trust Maryland Inventory of Historic Properties Form

Inventory No. ~~21-219~~ M: 21-219

1. Name of Property (indicate preferred name)

Historic Larcombe House

Other Wenham, Oakmont Manor, Four Chimney Estates

2. Location

Street & number 125 Central Ave not for publication

City, town Gaithersburg vicinity

County Montgomery

3. Owner of Property (give names and mailing addresses of all owners)

Name MARYLAND DEVELOPMENT CO LLC

Street & number 2401 RESEARCH BLVD STE 200 telephone

City, town Rockville state MD zip code 20850-3246

4. Location of Legal Description

Courthouse, registry of deeds, etc. MONTGOMERY COUNTY

City, town Gaithersburg liber 19809 folio 182 tax map FT61 tax parcel P719

Tax ID number

5. Primary Location of Additional Data

☐ Contributing Resource in National Register District
☐ Contributing Resource in Local Historic District
☐ Determined Eligible for the National Register/Maryland Register
☐ Determined Ineligible for the National Register/Maryland Register
☐ Recorded by HABS/HAER
☐ Historic Structure Report or Research Report at MHT
☐ Other

6. Classification

Category	Ownership	Current Function	
[x] Buildings	[x] Private	Vacant / not in use	
Resource Count		Contributing	Noncontributing
Buildings		1	0
Sites		0	0
Structures		0	0
Objects		0	0
Total		1	0

Number of Contributing Resources previously listed in the Inventory

7. Description

Inventory No. 21-219

Condition:	excellent altered	[x] good	fair	deteriorated	ruins
-------------------	----------------------	------------	------	--------------	-------

Prepare both a one-paragraph summary and a comprehensive description of the resource and its various elements, as it exists today.

1. **Architectural Classification:** Colonial Revival
2. **Materials**
 - a. Foundation: brick and cement Walls:
 - b. Interior: Plaster
 - c. Exterior: Clapboard
3. **Roof:** Copper and asphalt Shingles
4. **Chimney:** Brick

The residence, located at 125 Central Avenue, was constructed in 1893.¹ The structure is a gorgeous three story modified square plan frame dwelling with a hip-roof, eight dormers and a widows walk. The property faces Southeast and sits gracefully abandoned atop a gently upward sloping hill (See attachment 2), approx 350 feet from Central Ave. The parcel where it resides is just shy of 5 acres and is sparsely populated with vegetation and several very large trees. The house boast well over 4,000 square feet² of living space, which includes eleven rooms in total; four bedrooms, formal living room, formal dining room, kitchen, and a fully finished 3rd floor divided into 4 finished rooms. The interior walls maintain their original lath and plaster surface throughout the house. The exterior walls are wood clapboard, three of the four sides are painted white, while the fourth sides needs scraping and painting; the hip-roof is covered in asphalt shingles, rolled copper on the widow's walk and addition. The foundation is block foundation with red brick covering all exposed outfacing areas. All windows are 6/6 double-hung sashes. The main entrance is accessed from five steps of poured cement, leading to a six by four foot platform. An early two-story addition (9'x14') projects to the Southwest. There are four handsome chimneys that frame the house with grace and honor. There are four entrances to the house with the main entrance being located on the Southeast side. The house is in fair condition and is waiting for someone to restore her to her original glory.

Further detailed description is provided under section titled additional documentation.

¹ This information was gained from the Montgomery county tax records.

² Maryland State tax records:

http://sdatcert3.resiusa.org/rp_rewrite/results.asp?streetNumber=141&streetName=Central&county=16&intMenu=2&SearchType=Street&submit4=SEARCH

Maryland Historical Trust

Maryland Inventory of Historic Properties Form

Inventory No. M:21-219

Name
Continuation Sheet

Number 7 Page 1

Detailed Description:

Looking at the house from the exterior facing the entrance, one will notice an addition to the left side of the house that spans both floors, and on the right side of the house an addition, which is now the library, is cobbled onto the house (this was recently removed from the house). The exterior is wood clapboard, 3 sides of the house have been painted white and is in reasonably good shape, the backside of the house has peeling paint and unpainted sections. As you enter the house from the main entrance you are greeted by a large open living room, approx 35 x 20 with fireplaces flanking both ends. You will see a large vandalized staircase that leads to the second floor. Walking through the living room and towards the back of the house brings you through a small hallway and into the dining room. The kitchen is completely destroyed and is of absolute no use. You will find bathrooms on all three levels. There is a full basement with oil heating unit and upgraded circuit breaker panel. Going to the second floor you will be greeted by 4 large square bedrooms and a stairway leading up to the third floor rooms. The third floor rooms are completely finished, however water damage abounds. On the way to the third floor there is a door that leads one up one more level to the widows walk. The roof of the house and the widows walk area has been vandalized; the cooper roof was torn away. The original dental molding on the exterior of the house is intact along with some of the clapboard siding, see attached photos. The library is an addition to the house, it sits on the right side of the house and has extensive built in bookshelves and an absolutely beautiful domed ceiling. The 4.15-acre parcel on which the property sits, has been recently subdivided into 6 lots, and has been vacant for over 3 years. Even though the property has been vacant the interior of the house is in fairly good shape. The largest extend of damage to the house has been water damage to the plaster ceilings on all three floors. The most severe water damage can be seen on the second floor. There is also some slight vandalism to the interior of the property and many broken windows. The property is fully intact and appears to have had fully functional electric and water and sewage working prior to being vacated.

Detailed Description

Mr. Larcombe constructed this Colonial Revival style house in 1893. Mr. Larcombe purchased several properties in the Gaithersburg area in the late 1800's. This particular property was and still is sitting on a 4.15-acre lot, which has been recently subdivided into 6 lots. The house is currently on the border of two of the lots. The house is approximately 40 feet wide and 40 feet deep. It has 2 ½ stories and 8 dormers on the hip roof. The house is stick constructed with wood clapboard siding. The siding is in relatively good shape some if it appears to be the original siding.

Approaching the house from the front one notices five very distinct architectural features that set the house apart from any other house in Gaithersburg. First, there are 4 chimneys that are symmetrically placed around the house, two on the right and two on the left sides of the house. The four chimneys balance the house very nicely matching the high roofline and complimenting the second feature of the house that is most noticeable, the dormers. Each side of the house has 2 dormers for a total of 8 that accent the hip roof line very nicely. The third item of significant architectural beauty is the widow's walk that sits on top of the hip roof and gives a grand view of the property. The fourth and fifth items are really

Maryland Historical Trust

Maryland Inventory of Historic Properties Form

Inventory No. M:21-219

Name
Continuation Sheet

Number 7 Page 2

beautiful woodworking details that show the attention to detail that the original craftsmen prided themselves on and added an extra statement, much like an exclamation point at the end of a sentence! Those details are the dental molding that runs around the entire roofline of the house and the beautifully ornate door pediment sitting over the front entrance. (see photo).

Two additions have been added to the house over the years. Facing the house from the front entrance and turning left to walk around the house, there is a two-story addition approximately 9 feet wide by 13 feet in depth.. On the opposite side of the house an addition in the shape of a former shed that was located on the property has been moved up against the house and currently serves as the library, this addition is approximately 13 feet by 15 feet.

Three of the four sides of the house have a coat of primer painted on them. The fourth side has severely cracking and peeling paint. The backside of the house has a porch that runs along approximately half the length of the house. The porch is in pretty poor shape and needs immediate attention to keep it from becoming unusable.

The widows walk area of the roof has recently been vandalized for the copper sheeting. The original copper roofing material and copper doorway have been stolen. The hip roof has replacement asphalt shingles. I would imagine that these were slate shingles when the house was originally constructed.

Window placements around the entire house are very symmetrical. The first and second story has windows that align with each other creating the very nice lines of the house. There is a stairway access to the basement of the house. This is under the porch on the back of the house. The house sits about 5 feet off the surface of the ground. When approaching the house one has to go up about 7 steps to get to the entrance.

The interior of the house is in "relatively" good shape. All of the walls throughout the house are the original plaster. The stairway and banister have been vandalized; the spindles and railing have been destroyed or knocked down. The surfaces of the steps are in good shape. There is severe water damage on the second and third floor ceilings. The first floor ceiling is in very good shape. Please see attached spreadsheet for house layout and room dimensions. In every room the wallpaper that was hanging is falling down and the paint is severely cracked and peeling in almost every room.

Entering the house one walks into a great room approx 35' x 19'. This room is flanked on both ends by fireplaces. The fireplace mantels have been removed or stolen. Throughout the house the original floors are in tact except for the great room. The floor in the great room was also recently vandalized and torn up. A beautiful dental crown molding lines the walls of the great room. In the great room the main staircase leads up the second floor. Passing by the staircase one enters a small hallway, turning left takes you to the back staircase and kitchen, going strait brings you into the Dining room. The Dining room has built in cabinets and a fireplace; the dental molding that was in place has been stolen.

Maryland Historical Trust

Maryland Inventory of Historic Properties Form

Inventory No. M:21-219

Name

Continuation Sheet

Number 7 Page 3

Leaving the dining room and going the kitchen one passes through an area that has room on the left for a pantry and on the right for a bathroom. The kitchen has not appliances and the cabinets that are there are of 1970s vintage.

As one passes through the entrances of each room the original doors, molding and trim are mostly in tact, except where they have been stolen.

Moving to the second floor, (See spread sheet with dimensions and layout) one finds an approximately 8' x 8' landing on top of the steps. From there one can go in one of four equally sized bedrooms. Each bedroom has dental crown molding and plaster walls. All ceilings in the first and second floor are 10 feet tall. Radiant heaters are located in each room of the house.

Moving to the third floor, one finds 4 rooms and a bathroom, (see spreadsheet with layout); all rooms on the third floor have plaster walls and have slanted ceilings and two dormer windows. The access to the widow's walk is also located on the third floor. Steep steps lead to the widow's walk that was once covered in green tinted copper sheeting.

The exterior grounds of the house have very few original features if any. The only out building is a garage, which appears to be built much later after the house was originally built. The structure is closed on 3 sides and open on the fourth.

There is a demolition permit currently pulled for this house, permit number 305613. I have contacted the developer and asked him to delay the process. He is willing to give the house away for free, however that would require moving the house off the lot or buying one of his subdivided lots. Mr. Ted Smart is the owner and the developer; his company is Maryland Development Corporation LLC. Mr. Smart and I have discussed purchasing one of his lots and I submitted a letter of intent to purchase that was not responded to.

I have received written estimates on the cost to move the house to one of his lots for \$49,000. I have also been in the process of securing construction loans to be able to buy a piece of his property, move the house and then restore the house to its original grandeur. If able I will be in a position to move the house to one of his lots 30 days after signing the contract. I have contracted Expert house movers in Sharptown MD to move the house. Hopefully there will be no loss or damage to the house during the move. The biggest areas of concern are the four chimneys. The house mover stated that if it looked like the chimneys needed to be shored up, he would add bracing around the chimneys for support. Once the house is moved, the foundation is poured; I plan on restoring the house back to its original shape. The restoration process will be sub-contracted out and will hopefully take no longer than 12 months.


Other than the house there is no other landmark or exterior building that has any historical significance. The house is located in the vicinity of the historic Washington Grove community.

Maryland Historical Trust Maryland Inventory of Historic Properties Form

Inventory No. M:21-219

Name
Continuation Sheet

Number 7 Page 4



8. Statement of Significance.

Inventory No. 21-219

Applicable National Register Criteria:

- A. ☒ Property is associated with events that have made a significant contribution to the broad patterns of our history
- B. ☐ Property is associated with the lives of persons significant in our past
- C. ☒ Property embodies the distinctive characteristics of a type, period, or method of construction or represents values, or represents a significant and distinguishable entity whose components lack individual distinction
- D. ☐ Property has yielded, or is likely to yield, information important to prehistory or history.

Criteria Considerations:

Property is:

- A. ☐ Owned by a religious institution or used for religious purposes
- B. ☐ Removed from its original location
- C. ☐ A birthplace or grave.
- D. ☐ A cemetery
- E. ☐ A reconstructed building, object or structure
- F. ☐ a commemorative property

Areas of Significance:

- 1. Architecture
- 2. Community Planning and Development

Periods of Significance:

- 1. 1893-1930

Specific dates:

- 1. 1893

Architect/Builder:

Construction dates:

- 1. 1893

Evaluation for:

 National Register X Maryland Register not evaluated

Prepare a one-paragraph summary statement of significance addressing applicable criteria, followed by a narrative discussion of the history of the resource and its context. (For compliance projects, complete evaluation on a DOE Form – see manual.)

Statement of Significance: This house is a fine example of late 19th Century Colonial Revival style architecture. The current Gaithersburg city hall is the only other known property of such style reminiscent of an era of quality craftsmanship and pride in workmanship. The house has substantial architectural and historical significance for Gaithersburg, Montgomery County and Maryland. The handsome four chimney design of the house is one of a very few in the entire state. The beautiful lines of the house combined with the 8 dormers and widows walk are truly features that few historic properties can claim.

The Larcombe House, constructed ca. 1893, represents a brief period during the late nineteenth century when the rural environs just beyond the City of Washington D.C.'s borders attracted wealthy

Maryland Historical Trust Maryland Inventory of Historic Properties Form

Inventory No. M:21-219

Continuation Sheet

Number 8 Page 1

District residents to build their exurban retreats in the picturesque farmland of Montgomery County, Maryland. Wenham, the summer residence and retreat for Washington D.C., businessman John S. Larcombe, was among a handful of country houses built before widespread development in the early twentieth century that transformed the Oakmont and Washington Grove areas into automobile-centered suburb of the District. The Larcombe House meets National Register Criterion A, as an unusual survivor from the pre-suburban period of Gaithersburg history when it was a mixture of farmlands and summer retreats, and criterion C, for its high degree of integrity as a fine example of an early Colonial Revival-style dwelling. The house's period of significance is from 1893 until the middle of the 20th Century, when ownership was under the Larcombe family. The history of this house provides keen insight into the development of Gaithersburg and its evolving real estate trends during the late nineteenth century, as well as the construction of an urban businessman's' summer retreat just beyond the Washington D.C. borders.³

History of Oakmont: Oakmont was platted in 1888 near Gaithersburg on a farm located between the Georgetown-Frederick Road on the west and a B&O Railroad stop on the east. It allied itself with the ideals and spirit of the Methodist Washington Grove Camp Ground Association directly to the east as the companion subdivision. The building lots closest to Washington Grove on Oakmont Street were developed from 1888 to 1910 into a compact viable rural village community with large lots on the wide streets lined with mature trees. Oakmont soon acquired the community store and post office and the local school. It has remained remarkably unchanged and intact to the present! Oakmont is sited on "The Branch Farm", part of the holdings of Revolutionary war hero Colonel Zadok Magruder, who built a brick house known as Mount Pleasant about 1807. In 1838, the house and the 437-acre parcel were sold by the estate of Robert Pottinger Magruder to Lemuel Clements.⁴

Lemuel Clements was born to Henry and Jane Clements in 1794 and died Nov 1, 1880. He married Elizabeth Gardiner of Howard County in 1818 and had seven children, including John Ambrose in 1825. John Ambrose Clements married widowed Amanda (Gloyd) Clements, the daughter of Rebecca (Swamley) and Samuel Gloyd of Logtown. John Clements home and farm was located on the east side of Frederick Road.

The Clements properties were desirable for their soil and water, but also for their location. The B&O Railroad was on the east boundary and the Georgetown Fredericktown road on the west. The metropolitan Branch of the B&O Railroad commenced operation in 1873, immediately attracting developers and businessmen like John S. Larcombe.

³ NRHP nomination form for 7819 Moorland Lane, Montgomery County Md

⁴ Maryland Historic Trust, State Historic Sites Inventory Form, Oakmont Historic District. Judy Christensen

Maryland Historical Trust

Maryland Inventory of Historic Properties Form

Inventory No. M:21-219

Continuation Sheet

Number 8 Page 2

The neighboring Washington Grove Campground Association was a very successful retreat; it attracted trainloads of daily visitors and other who stayed on the grounds in tents, cottages or the Grove Hotel.

After Lemuel Clements' died in 1880, The Montgomery County Sentinel carried notices of the estate sale of Lemuel Clements real estate on March 18, 1881 and subsequent issues. A 110-acre farm identified as "The Branch Farm" was to be sold at auction on April 6th, 1881 to highest bidder. Another of Lemuel's sons, Peter Henry Clements, was the executor of the will. The property is described as:

"... located on the public road leading from the Georgetown to Frederick, four miles from Rockville and one mile from Gaithersburg, and within one hundred yards of the Washington Grove Station... and adjoins the lands for John Ambrose Clements and William R Easton.

This land is well wooded and watered, under good enclosure, and has a good apple orchard on it.

The buildings consist of a comfortable log dwelling, stable, Corn House, and other accessory outbuildings. The good natural quality of the soil, and the eligible location of this farm, being almost immediately on the line of the Metropolitan Railroad and its proximity to the thriving town of Gaithersburg, render it most desirable property."

John Ambrose Clements purchased the property in consideration of \$2,130.60, and in June of 1888 Lemuel's widow Jane Al Clements released all claim to the dower rights to land conveyed to John A. Clements by Lemuel Clements on July 12th, 1881 for the sum of \$568.00.⁵

Shortly before, on June 23, 1888, John Ambrose Clements and his wife Amanda sold 126 acres of land to two entrepreneurs, Henry Beard and James Craighead of Washington D.C. for \$8,190.⁶

Although Craighead and Beard were not directly connected to the Methodist Campgrounds, their new enterprise followed its principals including deed covenants against the manufacture or sale of spirits and the sale of a block of land to the Association for \$1.00 at the northeast corner of the parcel (corner of Deer Park Road and the railroad)⁷

The Oakmont developers offered the lots for sale outright and would finance the purchase with a deed of trust. Because of the more permanent nature of this village and the developers' gift to the Board of Education of lot 10, Block 4, for a school and the front 100 feet of the park to the B&O for a new

⁵ Land records RBP24/264 1888

⁶ Land records JA1/221 1886

⁷ Edwards, op cit pp 108-114

Maryland Historical Trust Maryland Inventory of Historic Properties Form

Inventory No: M:21-219

Continuation Sheet

Number 8 Page 3

station, the local school, post office and store were soon locate in the Oakmont area rather in the Washington Grove area.

Beard and Craighead lost no time. The Montgomery County Sentinel of July 13, 1888 noted "The tract of land opposite Washington Grove Campground, this county, recently purchased by Mr. Henry Beard (sic) of John A. Clements, is now being surveyed by Mr. G. Minor Anderson, and laid off into streets, broad avenues and building lots." The survey was recorded and entered into Montgomery County Plat Book A, page 20 on Oct 31st, 1888.

Central Avenue bisected the rectangular parcel from Frederick Road (Rt. 355) to an oval drive that fronted on the railroad station across the tracks. The interior of the Oval was labeled "Park" which the plat "dedicated for public recreation - no permanent buildings are to be erected thereon, no spirituous liquors or intoxication are to be sold or given away therein." On either side of the oval was an undivided block. The north block was labeled "Property of Washington Grove Camp Ground Association" and the south block was labeled 1. Blocks 2,3 and 4 were subdivided into 14 to 17 rectangular building lots. (See plat picture) Oakmont west of the intersection of Central Avenue and Chestnut Street (Now Oakmont St) was labeled "LAND NOT YET SUBDIVIDED" and was held by several landholders. One of those landholders was John S. Larcombe.

On Feb 24th, 1890, John S. Larcombe purchased 10 acres of land on the north side of Central Avenue for \$1,800. At that time, the property was recorded and identified as land not yet subdivided.⁸ Larcombe built the large three-story hip-roofed house that is the subject of this proposal submission. John S. Larcombe went on to purchase several other plots. He bought another 10-acre parcel at the corner of Central Ave and Frederick Road⁹ and lots 11, 12, and 13 in block 4, lots 10,11,12,13,14,15, and 16 in block 3 and lots 13,14,15,16 and 17 in block 2.¹⁰ Larcombe's property was not sold and developed until the mid 1930s upon his death.¹¹

⁸ Land records JA 17/101 1890

⁹ Land records TD24/486 1903

¹⁰ Land records 210/386 1910, 224/394 1911, and 226/152 1912

¹¹ Maryland Historic Trust, State Historic Sites Inventory Form, Judy Christensen

Maryland Historical Trust Maryland Inventory of Historic Properties Form

Inventory No. M:21-219

Continuation Sheet

Number 8 Page 4

John S. Larcombe was a wealthy Washington D.C. businessman. Larcombe enjoyed traveling to the Washington Grove area in the summer to live in the property that the family named Wenham. Larcombe's phone number was listed as "phone No 32 Gaithersburg".¹² John S. Larcombe was a very successful construction contractor in Washington D.C. Mr. Larcombe earned a reputation as a quality craftsman, some of his work that can still be seen today is the construction of the magnificent church near Catholic University, the beautiful edifice is 140 feet square with a lofty central dome. Under the grad line three chapels were built. Two of them are exact reproductions of the chapels of Bethlehem and Nazareth, drawings of which were made by Architect Cav. Aritides Leonori, of Rome Italy who visited the Holy Land for this purpose.¹³

John Larcombe was a member of the Riggs National Bank Board of Directors. He owned real estate through the Washington D.C. area also. Upon his death on Nov 8th, 1930, Larcombe had amassed a wealth of over \$400,000¹⁴

¹² Social Register, Summer 1919 (Vol 33: No. 75; June 1919). New York, NY: Social Register Assn, 1919.

¹³ Washington Post, August 21st, 1898, pg 14

¹⁴ Washington Post, Nov 15th, 1930, pg 3. His son John Larcombe Jr. was a successful golfer and business man.

9. Major Bibliographical References

Inventory No. 21-219

Maryland Historical Trust, State Historic Sites Inventory Form, Oakmont Historic District, Judy Christensen, 1991.

Washington Post

Census Data

Montgomery County Land records

10. Geographical Data

- A. Acreage of surveyed property 4.15 Acres
- B. Acreage of historical setting 4.15
- C. Quadrangle name
- D. Quadrangle scale:
- E. UTM: 4334014 311474 18S
- F. LAT / LONG: N 39.134916 W 77.181222 (see attached map)

Verbal boundary description and justification:

The property is bounded by a 359.85' boundary along Central Avenue, to the east the 509-foot property line along lot's 16 and 17, the property line to the west is 550' long running against Oakmont Manor properties, 36,38,39 and 40. The property line on the north is approximately 358 feet in length. (See attached plot) The house sits approximately 350 feet on the North side of Central Avenue

The property is currently on a subdivide parcel based on a permit approved by the Montgomery County Maryland Department of Permitting Services Approved on Nov 17th, 2004 (signature unreadable)

11. Form Prepared by

Name/title Jim Pietila

Organization None

Date: Originally submitted Feb 1st, 2005, revised Mar 15th 2005

Street & number:

21501 Goshen Hunt Lane

Telephone

240-683-6495

City or town Gaithersburg

State

MD

The Maryland Inventory of Historic Properties was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.


The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to: Maryland Historical Trust
DHCD/DHCP
100 Community Place
Crownsville, MD 21032-2023
410-514-7600

M: 21-219


LARCOMBE HOUSE, 125 CENTRAL AVENUE

Approx Total Sq Feet 3218.75




1st Floor

Room	Depth	Width	Sq Ft
Kitchen	15	11.5	172.5
Dining Rm	15.5	16.5	255.75
Living Rm	19	35	665
Office	13	8	104
Bathroom	6	12	72
Pantry	6	8	48
Library	13	15	195



2nd Floor

Mstr Bdrm	18	15.5	279
Bdrm 2	13	16	208
Bdrm 3	13	15.5	201.5
Bdrm 4	15	11.5	172.5
Bathroom	12	6	72
Mstr Btrm	13	8	104




3rd Floor

Bdrm 5	13.5	12.5	168.75
Bdrm 6	17.5	12.5	218.75
Bdrm 7	10.5	8.5	89.25
Bdrm 8	11.5	10.5	120.75
Bathroom	6	12	72

43,560

Lot Number	Sq Ft	Acerage
56	35000	0.803489
57	45673	1.048508
58	29783	0.683724
59	30000	0.688705
60	30000	0.688705
61	27500	0.631313
197956	4.544444	



OWNER/APPLICANT
 M&H DEVELOPMENT CO.
 2400 RESEARCH BLVD., SUITE 200
 ROCKVILLE, MARYLAND 20850
 PH: 301.840-0824

PROJECT DEVELOPMENT PLAN
 Parcels 688 & 719
FOUR CHIMNEY ESTATES
 LOT 1-10
 SUBDIVISION DISTRICT - MONTGOMERY COUNTY - MARYLAND

NO.	DATE	DESCRIPTION	BY



Macris, Hendricks & Glascock, P.A.
 Engineers • Planners
 Landscape Architects • Surveyors

6220 Wiggman Road, Suite 120
 Montgomery Village, Maryland
 20886-1278

Phone: 301.870.0840
 Fax: 301.848.0663
 www.mhgc.com

Proj. Mgr.	Designer
Date	Scale
Project No.	Sheet

125 CENTRAL

LARCOMBE HSE
 SUBDIV
 M.21-219

M: 21-219

LARCOMBE HOUSE

125 CENTRAL AVE

GAITHERSBURG



Map compiled on March 07, 2005 at 1:28 PM | Site located on base sheet no - 223NW09

NOTICE


The planimetric, property, and topographic information shown on this map is based on copyrighted Map Products from the Montgomery County Department of Park and Planning of the Maryland-National Capital Park and Planning Commission, and may not be copied or reproduced without written permission from M-NCPPC.

Property lines are compiled by adjusting the property lines to topography created from aerial photography and should not be interpreted as actual field surveys. Planimetric features were compiled from 1:14400 scale aerial photography using stereo photogrammetric methods.

This map is created from a variety of data sources, and may not reflect the most current conditions in any one location and may not be completely accurate or up to date. All map features are approximately within five feet of their true location. This map may not be the same as a map of the same area plotted at an earlier time as the data is continuously updated. Use of this map, other than for general planning purposes is not recommended. - Copyright 1998


MONTGOMERY COUNTY DEPARTMENT OF PARK AND PLANNING
THE MARYLAND-NATIONAL CAPITAL PARK AND PLANNING COMMISSION
8787 Georgia Avenue - Silver Spring, Maryland 20910-3700

Key Map




1 inch = 400 feet
1:4800

M:21-219



M:21-219



Gaithersburg Quad
1923 USGS

M:21-219



View from Central Ave




Southeast (front) façade
(Structure on right side has been
moved from the property)




Detail of front entrance

M:21-219



Southwest side of residence



Northeast side of property



View from main entrance doorway
looking toward back of house.



Northwest (rear) Façade
with partial porch